

Table 1: SAFETY OBSERVATION REPORT

| | | | | | | |
|--|--|-----------------------------------|-----------------------------------|-------------------------|---------------------------|----------------|
| Observers: Ken Krasner, Peter Wanderer, Ray Roberts | | Date: 02/29/08 | Duration: 45 Minutes | | | |
| Observation Categories | Observation Questions: | | | | | |
| POS | In risky position relative to task? No Exposed to risks of temperature/electricity/gas/chemicals/radiation? No Protection OK? Yes | | | | | |
| ERG | Risks from: posture, repetitive motion, load, vibration, temperature, lighting, noise, work flow? There were no risks from Load, and work flow during the lifting of the girders. | | | | | |
| PPE | Correct PPE? Yes, safety glasses and cautions signs displayed (Danger Visible/invisible laser radiation; caution laser radiation; Danger High voltage keep away; danger high current; danger remote controlled equipment) In safe condition? yes All parts of the body properly protected? Yes | | | | | |
| T&E | Is tool, equipment or facility right for the job? Yes In safe condition? yes Used correctly? Yes, air pads; Crane, and one scale | | | | | |
| PRO | Is there a standard procedure? Yes Is procedure adequate? Yes Up to date? Yes, 2/28/2008, # LS-II-PSRF-Girder-0008 Understood? Yes Followed? Yes | | | | | |
| ORD | Is workplace orderly? Yes Adequate space? Yes, work area is approximately 12ft.(w) * 18ft. (L) Is there a place for all materials and equipment? Yes All in its place? | | | | | |
| ASF | No unsafe acts or conditions identified No | | | | | |
| Work Area or Location | Number of Contacts | Description of unsafe acts | Observation Category | Follow-up Action | Person Responsible | By Date |
| Annex | 5 People | N/A | Lifting 2 girders with 4 air pads | N/A | | 2/29/08 |
| Annex (Quadrupole magnet) | 2 People | N/A | Gathering and setting data points | N/A | | 2/29/08 |
| Annex (Testing two magnets) | 1 Person | N/A | Data gathering | N/A | | 2/29/08 |